


# La Push Marina

- Commercial and sports fishing
  - 95 slips (1/2 commercial)
- Dock system upgrades were made in winter 2025
  - Replacement of wood decking
  - Replacement of creosote piles
  - Upgraded water and electrical lines
  - Replacement of gangways
- Several key infrastructure components still require replacement/upgrades and long-term considerations. These are crucial components of the Harbor Improvement Plan



## Hoist (loading) Dock Repairs and Replacement

- Existing hoist/loading dock was not replaced with the improvements made in 2025.
- Hoist crane system broke in Spring 2025; currently using temporary solution
- Requires:
  - Structural assessment
  - Identification of reusable components
  - Long term cost-effective replacement strategy



## Retaining Wall Stabilization

- Undermining of retaining wall supporting fuel infrastructure
- Failure would disrupt fuel access and marina operations and potential for significant environmental harm
- Requires:
  - Design of a long-term, resilient retaining wall to protect integrity of marina infrastructure



## Harbormaster Facilities

- Marina currently lacks harbormaster office and basic user facilities; operating out of temporary structure
- Considerations:
  - Harbormaster office
  - Retail space
  - Restrooms and showers facilities
  - Parking lot improvements



## Restaurant Deck Replacement

- Replacement of the deck would enable outdoor dining expansion
- Increase capacity during peak tourism season

### Considerations:

- Structural condition
- Repair vs. replacement options
- Feasibility
- Permitting



# Other Considerations:

- Ice Facility Improvements: current ice facilities are inadequate.
- Fish Processing Plant Improvements
- Erosion along riverside shoreline from breakwater wall, to restaurant and fish plant; assessment

